

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	3 January 2017
Time:	14:00
Inspection No.:	164

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Adequate water was sprayed on the surface of breaking operation observed at SA340. (Closed)</li> <li>Stagnant water found at SA340 was removed. (Closed)</li> <li>Construction wastes found near existing vegetation at SA340 were removed. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Construction materials and wastes were found near existing vegetation at SA320. The Contractor should remove the construction materials and wastes to keep the site clean and tidy.</li> <li>General refuse was found scattered on ground at SA320. The Contractor should remove the general refuse and keep the site clean and tidy.</li> <li>Chemical container without drip tray was found at SA320. The Contractor should provide secondary containment to avoid potential leakage.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		3 January 2017
Checked by	Y W Fung	/	3 January 2017

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	10 January 2017
Time:	14:00
Inspection No.:	165

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Construction materials and wastes found near existing vegetation at SA320 were removed. (Closed)</li> <li>General refuse found scattered on ground at SA320 was removed. (Closed)</li> <li>Chemical container without drip tray found at SA320 was provided with secondary containment. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Water sprayed on open site areas was found inadequate at SA324 and SA320. The Contractor should spray the open site areas with adequate water to prevent windblown dust emission.</li> <li>Construction wastes and materials were found scattered on ground at SA325 and SA326. The Contractor should remove the construction wastes and materials to keep the site clean and tidy.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		10 January 2017
Checked by	Y W Fung	/	10 January 2017

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	19 January 2017
Time:	14:00
Inspection No.:	166

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Adequate water was sprayed on open site areas at SA324 and SA320. (Closed)</li> <li>Construction wastes and materials found scattered on ground at SA325 and SA326 were removed. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Construction wastes were found scattered on ground at SA326. The Contractor should remove the construction wastes to keep the site clean and tidy.</li> <li>Public access road at SA328 was observed dusty. The Contractor should provide sufficient measures to keep the public access road clear of dusty materials.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		19 January 2017
Checked by	Y W Fung	/	19 January 2017

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	24 January 2017
Time:	14:00
Inspection No.:	167

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Construction wastes found scattered on ground at SA326 were removed. (Closed)</li> <li>Dusty materials observed along the public access road at SA328 were cleared. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Silts and debris were found near the entrance of drainage system at NB76. The Contractor should remove the sandy materials and implement measures to prevent silts and debris from entering the drainage system.</li> <li>Exposed stockpile of dusty materials were found at SA340. The Contractor should cover the stockpile entirely by impervious sheeting.</li> <li>Stagnant water was found at SA340. The Contractor should remove the water or apply larvicidal oil to prevent mosquito breeding.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam	<i>Sammi Lam</i>	24 January 2017
Checked by	Y W Fung	/	24 January 2017