Location: NM1 (Tai Kwong Secondary School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measur	ed Noise Le	vel for 30-mir	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1/28/2010	14:30	64.7	66.8	62.4	64.2	55.1	70	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measur	ed Noise Le	vel for 30-mir	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
1/28/2010	10:00	67.1	69.7	61.6	68.1	-	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

		Measur	ed Noise Le	vel for 30-mii	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1/	/28/2010	15:30	66.8	69.8	63.1	64.8	62.5	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measur	ed Noise Lev	vel for 30-mir	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1/28/2010	10:28	69.7	71.8	65.3	67.4	65.8	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measur	ed Noise Lev	vel for 30-mir	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1/28/2010	11:30	64.2	65.9	61.2	65.2	-	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measur	ed Noise Le	vel for 30-mir	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
1/28/2010	14:00	66.4	68.4	63.5	64.5	61.9	70	N

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

I		Measur	ed Noise Lev	vel for 30-mir	n, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
	1/28/2010	9:30	55.3	56.9	52.6	61.5	-	75	N

Remarks

^{* +3}dB(A) Façade effect correction included

^{**} Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level