

Location : NM1 (Tai Kwong Secondary School Rooftop - Façade)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 16-Mar-10 | 10:30 | 64.8 | 66.5 | 62.5 | 64.2 | 55.9 | 70 | N |

Location : NM2 (38 Ha Wun Yiu G/F - Free Field)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A)* | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|------------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq* | L10* | L90* | | | | |
| 16-Mar-10 | 9:50 | 66.2 | 69.0 | 64.0 | 68.1 | - | 75 | N |

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 16-Mar-10 | 13:05 | 65.7 | 68.0 | 63.5 | 64.8 | 58.4 | 70 | N |

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 16-Mar-10 | 11:30 | 67.7 | 70.5 | 64.0 | 67.4 | 55.9 | 75 | N |

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 16-Mar-10 | 11:00 | 64.4 | 65.9 | 63.0 | 65.2 | - | 75 | N |

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A)* | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|------------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq* | L10* | L90* | | | | |
| 16-Mar-10 | 10:00 | 63.5 | 66.6 | 62.6 | 64.5 | - | 70 | N |

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Calculated Construction Noise | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|-------------------------------|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 16-Mar-10 | 9:05 | 60.0 | 62.1 | 57.5 | 61.5 | - | 75 | N |

Remarks

* +3dB(A) Façade effect correction included

** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level