Location: NM1 (Tai Kwong Secondary School Rooftop - Facade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
22-Mar-10	11:00	65.8	67.5	63.5	64.2	60.7	70	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
22-Mar-10	9:55	67.5	69.5	61.5	68.1	-	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
22-Mar-10	13:00	64.9	68.0	63.0	64.8	48.5	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	/el for 30-ı	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
22-Mar-10	13:15	67.0	70.2	65.0	67.4	-	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
22-Mar-10	11:30	64.5	66.0	62.5	65.2	-	75	N

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured I	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
22-Mar-10	10:30	66.8	70.0	64.0	64.5	62.9	70	N

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
22-Mar-10	9:25	59.8	61.6	56.9	61.5	-	75	N

Remarks

^{* +3}dB(A) Façade effect correction included

^{**} Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level