Location: NM1 (Tai Kwong Secondary School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
3-May-10	10:30	66.4	68.1	63.5	64.2	62.4	70	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
3-May-10	13:50	67.3	69.0	63.2	68.1	-	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
3-May-10	13:10	67.1	69.2	63.4	64.8	63.2	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
3-May-10	13:00	68.0	70.1	64.0	67.4	59.1	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
3-May-10	11:10	65.2	67.1	62.4	65.2	-	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
3-May-10	11:20	67.1	69.0	64.2	64.5	63.6	70	N

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	/el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
3-May-10	10:00	58.4	60.1	53.4	61.5	-	75	N

Remarks

* +3dB(A) Façade effect correction included

^{**} Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level