Location : NM1 (Tai Kwong Secondary School Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
13-May-10	11:35	65.8	68.0	62.5	64.2	60.7	70	N

Location : NM2 (38 Ha Wun Yiu G/F - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
13-May-10	10:25	66.7	69.5	64.5	68.1	-	75	Ν

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
13-May-10	14:45	64.5	67.0	62.0	64.8	-	70	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
13-May-10	14:15	68.5	70.5	65.0	67.4	62.0	75	N

Location : NM5 (The Paragon Clubhouse Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
13-May-10	13:35	64.8	66.5	63.0	65.2	-	75	N

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
13-May-10	11:15	63.9	65.5	62.0	64.5	-	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-ı	min, dB(A	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
13-May-10	9:50	59.0	61.5	56.5	61.5	-	75	N

Remarks

* +3dB(A) Façade effect correction included

** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level