Location : NM1 (Tai Kwong Secondary School Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measu	red Noise Le	el for 30-min	, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
16-Jul-10	11:05	66.0	68.0	62.5	64.2	61.3	70	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measu	red Noise Le	vel for 30-min	. dB(A)	Baseline Noise	Calculated Construction	Limit Level.	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
16-Jul-10	11:35	65.5	67.7	62.1	68.1	-	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measu	red Noise Le	el for 30-min	, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
16-Jul-10	11:20	64.7	67.0	61.0	64.8	-	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measu	red Noise Le	vel for 30-min	, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
16-Jul-10	13:00	66.0	67.5	64.0	67.4	-	75	N

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

Γ		Measu	red Noise Le	vel for 30-min	, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
L	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
Γ	16-Jul-10	13:15	63.4	65.5	61.5	65.2	-	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measu	red Noise Lev	vel for 30-min	, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
16-Jul-10	10:40	64.7	66.5	62.0	64.5	51.2	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measu	red Noise Lev	el for 30-min	, dB(A)	Baseline Noise	Calculated Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
16-Jul-10	9:55	57.7	60.0	54.7	61.5	-	75	N

Remarks

- +3dB(A) Façade effect correction included
- ** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level