Location: NM1 (Tai Kwong Secondary School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Level, dB(A) | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 13:50 | 65.8 | 67.5 | 64.0 | 64.2 | 60.7 | 70 | N |

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Level, dB(A)* | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 13:10 | 63.9 | 66.4 | 60.1 | 68.1 | - | 75 | N |

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Level, dB(A) | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 11:15 | 64.2 | 66.5 | 61.2 | 64.8 | - | 70 | N |

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Level, dB(A) | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 11:10 | 64.7 | 65.5 | 63.0 | 67.4 | - | 75 | N |

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Level, dB(A) | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 13:00 | 63.8 | 65.0 | 62.0 | 65.2 | - | 75 | N |

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Level, dB(A)* | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 10:30 | 67.2 | 69.0 | 64.5 | 64.5 | 63.9 | 70 | N |

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise | Calculated Construction | Limit Level, | Exceedance |
|-----------|--|------|------|------|----------------|-------------------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Level, dB(A) | Noise Level, dB(A) ** | dB(A) | (Y/N) |
| 11-Oct-10 | 14:30 | 61.4 | 63.0 | 58.5 | 61.5 | - | 75 | N |

Remarks

+3dB(A) Façade effect correction included

^{**} Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level