

Location : NM1 (Tai Kwong Secondary School Rooftop - Façade)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A) | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq  | L10  | L90  |                             |   |                    |                  |
| 27-Oct-10 | 10:35                                  | 64.4 | 66.5 | 62.0 | 64.2                        | 50.9  | 70                 | N                |

Location : NM2 (38 Ha Wun Yiu G/F - Free Field)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A)* | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|------------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq* | L10* | L90* |                              |   |                    |                  |
| 27-Oct-10 | 10:19                                  | 69.5 | 71.5 | 65.0 | 68.1                         | 63.9  | 75                 | N                |

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A) | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq  | L10  | L90  |                             |   |                    |                  |
| 27-Oct-10 | 13:50                                  | 66.0 | 68.0 | 62.5 | 64.8                        | 59.8  | 70                 | N                |

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A) | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq  | L10  | L90  |                             |   |                    |                  |
| 27-Oct-10 | 13:00                                  | 67.1 | 69.5 | 64.0 | 67.4                        | -   | 75                 | N                |

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A) | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq  | L10  | L90  |                             |   |                    |                  |
| 27-Oct-10 | 13:30                                  | 63.5 | 65.0 | 61.5 | 65.2                        | -   | 75                 | N                |

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A)* | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|------------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq* | L10* | L90* |                              |   |                    |                  |
| 27-Oct-10 | 11:05                                  | 65.1 | 66.5 | 64.0 | 64.5                         | 56.2  | 70                 | N                |

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)  
 Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date      | Measured Noise Level for 30-min, dB(A) |      |      |      | Baseline Noise Level, dB(A) | Calculated Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|---|--------------------|------------------|
|           | Start Time                             | Leq  | L10  | L90  |                             |   |                    |                  |
| 27-Oct-10 | 9:34                                   | 61.2 | 62.5 | 58.5 | 61.5                        | -   | 75                 | N                |

Remarks

\* +3dB(A) Façade effect correction included

\*\* Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level