Location: NM1 (Tai Kwong Secondary School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Meas	ured Noise Lev	vel for 30-min,	dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
19-Nov-10	11:35	64.8	66.5	62.5	64.2	55.9	70	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
19-Nov-10	11:45	68.8	70.5	64.0	68.1	60.5	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
19-Nov-10	13:15	65.8	67.5	63.0	64.8	58.9	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Meas	ured Noise Le	vel for 30-min,	dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
19-Nov-10	13:00	67.2	69.5	64.0	67.4	-	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Meas	ured Noise Le	vel for 30-min,	dB(A)	Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
19-Nov-10	16:15	62.6	64.5	60.0	65.2	-	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Calculated	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
19-Nov-10	15:30	65.1	66.0	63.5	64.5	56.2	70	N

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

Ī		Meas	ured Noise Le	vel for 30-min.	dB(A)	Baseline Noise	Calculated	Limit Level.	Exceedance
	Date	Start Time	Lea	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
	19-Nov-10	10:13	59.0	60.5	57.5	61.5	-	75	N

Remarks

^{* +3}dB(A) Façade effect correction included

^{**} Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level