

Location : NM1 (Tai Kwong Secondary School Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|--|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 24-Dec-10 | 10:14 | 64.9 | 66.5 | 63.0 | 64.2 | 56.6 | 70 | N |

Location : NM2 (38 Ha Wun Yiu G/F - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A)* | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|------------------------------|--|--------------------|------------------|
| | Start Time | Leq* | L10* | L90* | | | | |
| 24-Dec-10 | 11:16 | 66.3 | 68.5 | 63.0 | 68.1 | 66.3 | 75 | N |

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|--|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 24-Dec-10 | 12:14 | 64.1 | 65.5 | 62.0 | 64.8 | 64.1 | 70 | N |

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|--|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 24-Dec-10 | 11:36 | 66.8 | 69.5 | 62.5 | 67.4 | 66.8 | 75 | N |

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|--|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 24-Dec-10 | 13:14 | 62.3 | 64.0 | 59.5 | 65.2 | 62.3 | 75 | N |

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A)* | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|------------------------------|--|--------------------|------------------|
| | Start Time | Leq* | L10* | L90* | | | | |
| 24-Dec-10 | 12:29 | 64.2 | 66.0 | 63.0 | 64.5 | 64.2 | 70 | N |

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| Date | Measured Noise Level for 30-min, dB(A) | | | | Baseline Noise Level, dB(A) | Corrected Construction Noise Level, dB(A) ** | Limit Level, dB(A) | Exceedance (Y/N) |
|-----------|--|------|------|------|-----------------------------|--|--------------------|------------------|
| | Start Time | Leq | L10 | L90 | | | | |
| 24-Dec-10 | 9:52 | 59.6 | 61.0 | 57.5 | 61.5 | 59.6 | 75 | N |

Remarks

* +3dB(A) Façade effect correction included

** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level