Location: NM1 (Tai Kwong Secondary School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
15-Apr-11	13:13	65.1	66.5	63.0	64.2	57.8	70	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
15-Apr-11	10:35	69.2	71.5	65.5	68.1	62.7	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
15-Apr-11	13:30	64.6	67.0	63.0	64.8	64.6	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
15-Apr-11	11:30	67.1	70.5	64.0	67.4	67.1	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
15-Apr-11	14:05	64.7	66.5	63.0	65.2	64.7	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Construction Noise	dB(A)	(Y/N)
15-Apr-11	11:17	65.9	68.0	63.0	64.5	60.3	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	Corrected	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Construction Noise	dB(A)	(Y/N)
15-Apr-11	9:55	58.9	61.0	56.5	61.5	58.9	75	N

## Remarks

<sup>\* +3</sup>dB(A) Façade effect correction included

<sup>\*\*</sup> Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level. If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level