Location : NM1A (168 Shek Kwu Lung Village G/F- Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

Γ		Meas	ured Noise Lev	/el for 30-min,	dB(A)	Baseline Noise	<b>Corrected Construction</b>	Limit Level,	Exceedance
	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
	1-Dec-11	11:21	66.1	68.0	63.5	64.2	61.6	75	Ν

Location : NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	<b>Corrected Construction</b>	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
1-Dec-11	15:06	69.4	72.0	67.0	68.1	63.5	75	N

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Meas	ured Noise Lev	vel for 30-min,	dB(A)	Baseline Noise	<b>Corrected Construction</b>	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	$dB(A)^{\#}$	(Y/N)
1-Dec-11	13:51	67.0	69.0	65.0	64.8	63.0	70	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				Baseline Noise	<b>Corrected Construction</b>	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1-Dec-11	13:00	67.4	69.5	65.0	67.4	67.4	75	N

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Meas	ured Noise Lev	vel for 30-min,	dB(A)	<b>Baseline Noise</b>	<b>Corrected Construction</b>	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1-Dec-11	15:49	65.3	67.0	64.0	65.2	48.9	75	N

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Meas	ured Noise Lev	vel for 30-min,	dB(A)	Baseline Noise	<b>Corrected Construction</b>	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A) <sup>#</sup>	(Y/N)
1-Dec-11	15:09	64.7	67.0	62.5	64.5	51.2	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured Noise Level for 30-min, dB(A)				<b>Baseline Noise</b>	<b>Corrected Construction</b>	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1-Dec-11	10:29	66.3	68.0	63.5	61.5	64.6	75	Ν

Remarks

\* +3dB(A) Façade effect correction included

# - Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.

\*\* Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level