Location: NM1A (168 Shek Kwu Lung Village G/F - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | el for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 6-Jun-12 | 15:33 | 65.1 | 66.9 | 62.3 | 64.2 | 57.8 | 75 | N |

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| ľ | | Mea | sured Noise Lev | el for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|---|----------|------------|-----------------|------------------|------|--------------|--------------|--------------|------------|
| | Date | Start Time | Leq* | L10* | L90* | Noise Level, | Construction | dB(A) | (Y/N) |
| ı | 6-Jun-12 | 14:58 | 64.7 | 67.6 | 61.8 | 68.1 | 64.7 | 75 | N |

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A)# | (Y/N) |
| 6-Jun-12 | 14:05 | 64.7 | 67.6 | 62.4 | 64.8 | 64.7 | 70 | N |

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 6-Jun-12 | 13:15 | 65.0 | 66.7 | 61.4 | 67.4 | 65.0 | 75 | N |

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 6-Jun-12 | 11:18 | 64.4 | 67.1 | 62.6 | 65.2 | 64.4 | 75 | N |

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Noise Level, | Construction | dB(A)# | (Y/N) |
| 6-Jun-12 | 10:35 | 65.2 | 66.9 | 62.8 | 64.5 | 56.9 | 70 | N |

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 6-Jun-12 | 9:50 | 64.3 | 67.0 | 61.8 | 61.5 | 61 1 | 75 | N |

Remarks

* +3dB(A) Façade effect correction included

- Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.

** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level