Location: NM1A (168 Shek Kwu Lung Village G/F - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|-----------|------------|-----------------|-------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 12-Jun-12 | 14:15 | 64.9 | 67.2 | 63.1 | 64.2 | 56.6 | 75 | N |

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | el for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|-----------|------------|-----------------|------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Noise Level, | Construction | dB(A) | (Y/N) |
| 12-Jun-12 | 15:17 | 65.7 | 68.2 | 64.0 | 68.1 | 65.7 | 75 | N |

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|-----------|------------|-----------------|-------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A)# | (Y/N) |
| 12-Jun-12 | 16:20 | 65.0 | 67.9 | 62.7 | 64.8 | 51.5 | 65 | N |

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | el for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 12Jun-12 | 17:06 | 66 1 | 67.3 | 64.2 | 67.4 | 66 1 | 75 | N |

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| I | | Mea | sured Noise Lev | el for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|---|-----------|------------|-----------------|------------------|------|--------------|--------------|--------------|------------|
| | Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| ĺ | 12-Jun-12 | 10:46 | 64.3 | 66.9 | 61.8 | 65.2 | 64.3 | 75 | N |

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|-----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Noise Level, | Construction | dB(A)# | (Y/N) |
| 12-Jun-12 | 11:28 | 65.6 | 67.2 | 62.7 | 64.5 | 59.1 | 65 | N |

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|-----------|------------|-----------------|-------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 12-Jun-12 | 9:50 | 65.6 | 66.4 | 62.3 | 61.5 | 63.5 | 75 | N |

Remarks

* +3dB(A) Façade effect correction included

- Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.

** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level