Location: NM1A (168 Shek Kwu Lung Village G/F - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 1-Nov-12 | 14:15 | 62.4 | 63.5 | 54.4 | 64.2 | 62.4 | 75 | N |

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Noise Level, | Construction | dB(A) | (Y/N) |
| 1-Nov-12 | 13:00 | 67.9 | 68.8 | 59.9 | 68.1 | 67.9 | 75 | N |

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| ſ | | Mea | sured Noise Lev | vel for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|---|----------|------------|-----------------|-------------------|------|--------------|--------------|--------------|------------|
| | Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A)# | (Y/N) |
| ı | 1-Nov-12 | 11:00 | 64.7 | 67.1 | 59.5 | 64.8 | 64.7 | 70 | N |

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 1-Nov-12 | 10:30 | 65.1 | 66.2 | 63.8 | 67.4 | 65.1 | 75 | N |

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 1-Nov-12 | 14:00 | 64.5 | 65.8 | 62.8 | 65.2 | 64.5 | 75 | N |

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | vel for 30-min, d | IB(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|-------------------|-------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq* | L10* | L90* | Noise Level, | Construction | dB(A)# | (Y/N) |
| 1-Nov-12 | 13:10 | 66.8 | 67.4 | 66.0 | 64.5 | 62.9 | 70 | N |

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

| | Mea | sured Noise Lev | el for 30-min, d | B(A) | Baseline | Corrected | Limit Level, | Exceedance |
|----------|------------|-----------------|------------------|------|--------------|--------------|--------------|------------|
| Date | Start Time | Leq | L10 | L90 | Noise Level, | Construction | dB(A) | (Y/N) |
| 1-Nov-12 | 9:55 | 58.6 | 59.8 | 56.5 | 61.5 | 58.6 | 75 | N |

Remarks

- * +3dB(A) Façade effect correction included
- # Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.
- ** Construction noise level is only calculated when Measured noise level (Leq) > Impact noise level.

 If Measured noise level < Impact noise level, Corrected noise level = Measured noise level