Location: NM1A (168 Shek Kwu Lung Village G/F- Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

ſ		Measure	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
L	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
	8-Aug-13	10:52	60.7	62.0	58.3	64.2	60.7	75	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measure	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
8-Aug-13	13:49	62.3	64.6	61.2	68.1	62.3	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)#	(Y/N)
8-Aug-13	10:43	64.0	66.4	62.1	64.8	64.0	70	N

Location: NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measure	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
8-Aug-13	9:48	64.1	66.2	62.3	67.4	64.1	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measure	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
8-Aug-13	13:58	62.5	64.4	60.4	65.2	62.5	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measure	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)#	(Y/N)
8-Aug-13	10:08	64.3	66.3	60.0	64.5	64.3	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measure	d Noise Lev	el for 30-m	in, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
8-Aug-13	11:40	61.7	63.6	59.6	61.5	0.0	75	N

Remarks

- * +3dB(A) Façade effect correction included
- # Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.
- * Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level