Location : NM1A (168 Shek Kwu Lung Village G/F- Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

Γ		Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
	18-Oct-13	13:12	63.2	65.4	61.1	64.2	63.2	75	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
18-Oct-13	11:26	62.1	64.2	60.4	68.1	62.1	75	N

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)#	(Y/N)
18-Oct-13	10:48	65.2	67.8	64.3	64.8	54.6	70	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
18-Oct-13	9:45	65.7	66.9	63.1	67.4	65.7	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
18-Oct-13	13:20	65.2	68.1	63.8	65.2	65.2	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A) [#]	(Y/N)
18-Oct-13	9:50	61.7	62.9	59.6	64.5	61.7	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
18-Oct-13	10:38	64.0	65.7	62.1	61.5	60.4	75	N

Remarks

- * +3dB(A) Façade effect correction included
- # Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.
- ** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level. If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level