Location: NM1A (168 Shek Kwu Lung Village G/F- Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
5-Nov-13	10:35	60.0	61.5	57.0	64.2	60.0	75	N

Location: NM2 (38 Ha Wun Yiu G/F - Free Field)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
5-Nov-13	10:00	62.3	63.8	60.1	68.1	62.3	75	N

Location: NM3 (Wong Shiu Chi Middle School Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A) [#]	(Y/N)
5-Nov-13	13:00	61.1	63.0	59.5	64.8	61.1	70	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
5-Nov-13	13:05	62.0	63.7	60.4	67.4	62.0	75	N

Location: NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

I		Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
l	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
I	5-Nov-13	11:30	61.7	63.0	60.5	65.2	61.7	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A) [#]	(Y/N)
E Nov. 12	10.EE	62.0	64.2	60.4	GA E	62.0	70	NI

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
5-Nov-13	9:40	57.7	59.0	56.5	61.5	57.7	75	N

Remarks

- * +3dB(A) Façade effect correction included
- # Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.
- ** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

 If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level