Location : NM1A (168 Shek Kwu Lung Village G/F- Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
4-Dec-13	10:46	63.1	64.6	61.2	64.2	63.1	75	N

Location : NM2 (38 Ha Wun Yiu G/F - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
4-Dec-13	11:30	67.5	69.3	63.8	68.1	67.5	75	N

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)#	(Y/N)
4-Dec-13	11:09	66.8	68.5	64.0	64.8	62.5	70	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

Ī		Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
ĺ	4-Dec-13	10:18	65.5	67.0	63.0	67.4	65.5	75	N

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
4-Dec-13	13:38	67.7	69.0	65.5	65.2	64.1	75	N

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)#	(Y/N)
4-Dec-13	13:26	62.5	63.9	60.1	64.5	62.5	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
4-Dec-13	14:26	60.2	62.1	57.9	61.5	60.2	75	N

## Remarks

- \* +3dB(A) Façade effect correction included
- # Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.

  \*\* Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

  If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level