Location : NM1A (168 Shek Kwu Lung Village G/F- Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	/el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
11-Jun-14	10:30	59.0	60.5	56.5	64.2	59.0	75	N

Location : NM2 (38 Ha Wun Yiu G/F - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
11-Jun-14	15:35	62.4	64.0	57.5	68.1	62.4	75	N

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	/el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A) [#]	(Y/N)
11-Jun-14	11:15	60.4	62.0	59.5	64.8	60.4	65	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
11-Jun-14	13:00	62.1	64.0	60.0	67.4	62.1	75	N

Location : NM5 (The Paragon Clubhouse Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
11-Jun-14	13:50	63.4	64.5	61.5	65.2	63.4	75	N

Location : NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	/el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A) [#]	(Y/N)
11-Jun-14	14:40	64.5	65.5	63.0	64.5	64.5	70	N

Location : NM7 (Riverain Bayside Switch Room Rooftop - Façade) Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
11-Jun-14	9:40	58.4	59.5	56.5	61.5	58.4	75	N

Remarks

* +3dB(A) Façade effect correction included

- Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.
** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level