Location : NM1A (168 Shek Kwu Lung Village G/F- Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
15-Jul-14	16:33	62.7	63.9	61.2	64.2	62.7	75	N

Location : NM2 (38 Ha Wun Yiu G/F - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)	(Y/N)
15-Jul-14	15:20	67.4	68.9	65.2	68.1	67.4	75	N

Location : NM3 (Wong Shiu Chi Middle School Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)#	(Y/N)
15-Jul-14	10:43	63.3	65.1	60.9	64.8	63.3	65	N

Location : NM4 (Uptown Plaza Block 4 Rooftop - Façade)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
15-Jul-14	13:40	65.2	67.1	62.6	67.4	65.2	75	N

Location : NM5 (The Paragon Clubhouse Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

		Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
	Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
1	15-Jul-14	12:58	65.5	67.2	63.1	65.2	53.7	75	N

Location: NM6 (PLK Tin Ka Ping Primary School near the entrance - Free Field)
Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	nin, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq*	L10*	L90*	Level, dB(A)*	Noise Level, dB(A) **	dB(A)#	(Y/N)
15-Jul-14	14:23	62.1	63.3	60.2	64.5	62.1	70	N

Location: NM7 (Riverain Bayside Switch Room Rooftop - Façade)

Day time 07:00-19:00 hrs Normal Weekdays Impact Noise Monitoring Results

	Measured	Noise Lev	el for 30-r	min, dB(A)	Baseline Noise	Corrected Construction	Limit Level,	Exceedance
Date	Start Time	Leq	L10	L90	Level, dB(A)	Noise Level, dB(A) **	dB(A)	(Y/N)
15-Jul-14	10:05	61.7	63.2	69.4	61.5	48.2	75	N

Remarks

- * +3dB(A) Façade effect correction included
- # Limit Level of 70dB(A) applies to education institutes while 65dB(A) applies during school examination period.
- ** Construction noise level is only calculated when Measured noise level (Leq) > Baseline noise level.

 If Measured noise level < Baseline noise level, Corrected noise level = Measured noise level