

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	5 June 2019
Time:	14:00
Inspection No.:	290

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Chemical containers without secondary containment observed at NB42A have been removed. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Inadequate spraying of water for dry exposed area was observed at SA340. The Contractor was advised to spray the dry exposed area with water regularly for dust suppression.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		5 June 2019
Checked by	Y W Fung	/	5 June 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	11 June 2019
Time:	14:00
Inspection No.:	291

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Adequate spraying of water for dry exposed area has been provided at SA340 for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Accumulation of general refuse was observed at SA328 and SA329. The Contractor was advised to segregate the wastes and dispose of regularly.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		11 June 2019
Checked by	Y W Fung	/	11 June 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	20 June 2019
Time:	14:00
Inspection No.:	292

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Accumulation of general refuse was observed at SA328 has been covered for temporary storage while that observed at SA329 has been removed. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Exposed stockpile of dusty materials without proper cover was observed at NB63A. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		20 June 2019
Checked by	Y W Fung	/	20 June 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	25 June 2019
Time:	14:00
Inspection No.:	293

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Exposed stockpile of dusty materials without proper cover observed at NB63A has been covered entirely with impervious sheeting for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		25 June 2019
Checked by	Y W Fung	/	25 June 2019